

Reprogramming Pre-J2534 Files

Please Note: The CID or Calibration ID number represents the number that the CID will become after applying the Pack file.

Affected Unit	Year	Vehicle	Engine	Aspiration	Transmission	Specification	Pack Number	Details	Necessary connector	CID
ECM	1999, 2000, 2001	Impreza	2.2L	non-Turbo	MT	FED, CAL	UD-S204 P1507		None	CID# is not available.
ECM	2000, 2001	Impreza	2.5L	non-Turbo	MT, AT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging	None	DU2IHGB3
ECM	2000, 2001	Legacy	2.5L	non-Turbo	MT	FED, CAL	UD-S204	P1507, P0172, P0065, P0031, P0130, P1133	None	CID# is not available.
ECM	2000, 2001	Outback	2.5L	non-Turbo	MT	FED, CAL	UD-S204	P1507, P0172, P0065, P0031, P0130, P1133	None	CID# is not available.
ECM	2000	Forester	2.5L	non-Turbo	MT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, Back fire, P0031, P0130, P1133	None	DU2IHSMC
ECM	2000	Forester	2.5L	non-Turbo	AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, Pinging, P1445, P0065, Back fire, P0031, P0130, P1133	None	DU2IHSAD
ECM	2000	Impreza	2.5L	non-Turbo	MT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, Back fire, P0031, P0130, P1133	None	DU2IHGB3
ECM	2000	Impreza	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, Back fire, P0031, P0130, P1133	None	DU2IHGB3
ECM	2000	Legacy	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0031, P0130, P1133, P0172, P0065	None	DU2IHL0C
ECM	2000	Outback	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0031, P0130, P1133, P0172, P0065	None	DU2IHK0C
ECM	2001	Forester	2.5L	non-Turbo	MT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, P0031, P0130, P1133	None	DU2IHSMC
ECM	2001	Forester	2.5L	non-Turbo	AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, Pinging, P1445, P0065, P0031, P0130, P1133, P1490	None	DU2IHSAD
ECM	2001	Impreza	2.5L	non-Turbo	MT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, P0031, P0130, P1133	None	DU2IHGB3
ECM	2001	Impreza	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, P0031, P0130, P1133	None	DU2IHGB3
ECM	2001	Legacy	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P0031, P0130, P1133	None	DU2IHL0C
ECM	2001	Outback	2.5L	non-Turbo	AT	FED, CAL	UD-S205A	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P0031, P0130, P1133	None	DU2IHK0C
ECM	2001	Outback	3.0L	non-Turbo	AT	FED, CAL	UD-S202	Long cranking, hesitation, Hard start(Step 2), Hard start(Step 1), P0464	E/G-1	D6JR000B
ECM	2002	Forester	2.5L	non-Turbo	MT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, P0031, P0130, P1133	None	DU2IHSMC
ECM	2002	Forester	2.5L	non-Turbo	AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, Pinging, P1445, P0065, P0031, P0130, P1133, P1490	None	DU2IHSAD
ECM	2002	Impreza	2.5L	non-Turbo	MT, AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, Pinging, P1445, P0065, P0031, P0130, P1133	None	DU2IHGS3
ECM	2002	Impreza	2.0L	Turbo	MT	FED, CAL	UD-S204	P030X(Step2), P030X(Step1), Pinging, P030X, P1443, P0457, P0340	E/G-1	A4SGE01C
ECM	2002	Impreza	2.0L	Turbo	MT, AT	FED, CAL	UD-S204	P030X(Step2)	E/G-1	A4SGE01C

Reprogramming Pre-J2534 Files

Affected Unit	Year	Vehicle	Engine	Aspiration	Transmission	Specification	Pack Number	Details	Neccesary connector	CID
ECM	2002	Impreza	2.0L	Turbo	AT	FED, CAL	UD-S204	Pinging, P030X, P1443, P0457, P0340	E/G-1	A4SGE01C
ECM	2002	Legacy	2.5L	non-Turbo	MT, AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, P1445, P0065	E/G-2	DU450L05
ECM	2002	Outback	2.5L	non-Turbo	MT, AT	FED, CAL	UD-S205B	P0172, P0065, P1443, P0172, Hesitation, After burn, P1445, P0065	E/G-2	DU450K05
ECM	2002	Outback	3.0L	non-Turbo	AT	FED, CAL	UD-S202	Long cranking, hesitation, P030X	E/G-2	D6HH000B
ECM	2003	Impreza	2.0L	Turbo	MT	FED, CAL	UD-S204	P030X(Step2), P030X(Step1)	E/G-2	A4TC401L
ECM	2003	Outback	3.0L	non-Turbo	AT	FED, CAL	UD-S202	Long cranking, hesitation	E/G-2	D6QK000B
ECM	2004	Outback	3.0L	non-Turbo	AT	FED, CAL	UD-S202	Long cranking, hesitation	E/G-2	D6PC000B